

Motorized Sailplanes

20 Years of Joy and Pain

**The Stations of the Cross towards
Freedom**

Brief History of Personal Experience since 1986

- turbo single seater 1986-1995**
- turbo double seater 1995-1998**
- self launch double seater 1998**

Also Experience of more famous:

- Steve Fossett (2003 & 2004)**
- Régis Kuntz + D. Hauss (2003)**
- Dick Johnson (1995 test starts with ‘Propulsion Failure’)**
- Greenwell, Flament, Pollard, Woodward, Serkowski,**
- and dozens of other ones**

44 FAILURES in 7 years (Rotax)

2,7 hours MTBF and 30 hours TBO

- **28 flights interrupted (or T.O.)**
- **14 flights to nearest APT**
 - ✓ **11 Ignition cables or connectors**
 - ✓ **6 fuel tanks leaking or burst**
 - ✓ **4 belt breaks**
 - ✓ **4 magneto coil failures**
 - ✓ **1 engine oil leakage**

COMPONENTS OF A THERMAL ENGINE POWER PLANT

1. Propeller
2. Reducer
3. Engine
4. Cooling circuit
5. Ignition system
6. Gasoline tanks and pipes
7. Pylon and its rotation device
8. Electrical generation and distribution
9. Control system and interlocks
10. Exhaust gas ducts and muffler

1. Propeller: Speed limit, temperature, balancing, brake pilot tolerant, insensitive to synchronization with engine, independent from belt.



First engine, first problem: One blade is self desintegrating because of speed and vibration (1986)



When broken (pilot's fault)
engine cannot be any more
fully retracted, outlanding may
become necessary

1. Propeller: the arrestor should be "fault tolerant", otherwise the problem becomes worse (new desing is OK)

COMPONENTS OF A THERMAL ENGINE POWER PLANT

1. Propeller
2. Reducer
3. Engine
4. Cooling circuit
5. Ignition system
6. Gasoline tanks and pipes
7. Pylon and its rotation device
8. Electrical generation and distribution
9. Control system and interlocks
10. Exhaust gas ducts and muffler

- No reducer means zero problem
- Gear means safe but no vibration tolerance
- V-Belt is vibration tolerant, allows slipping, high torque capacity
- Tooth belt has low torque capacity, low vibration tolerance, low elasticity
- Kevlar containing belt should NOT be used on alternate torque (manufacturer's statement)

CONCLUSION: Most plants use Kevlar based tooth belts.....

ACCORDING TO THE MANUFACTURER (GATES):

1. The speed limit on the 25 teeth pulley is 5.500 rpm against 7.100 rpm actual.
2. Not belt tensioner should be applied on the back side. There are 4 rolls diameter 20mm.
3. Even considering 5.500 rpm, the service factor would be only 2. Aircrafts drives require minimum 5 better 7.
4. Polyurethane-Kevlar belts are not usable on alternate motion. Neoprene-Glass fibre YES.

The 2 safest drives have no drive or simple gear reducer

Ventus T



ASH 25E



Two excellent trouble-free V-belt drives


Ventus CM



DG 1000 T



Kevlar tooth belt after 25 hours average life




Manufacturer gives a life time of 10.000 hours if application is correct. Old glass fiber belts look like new after 7 years.



The centrifugal friction is a costly and heavy solution

All Solo engines



Problem was also solved using the original and more flexible 10 years old design fiberglass tooth belt.

But setting of tension is difficult because of too short available adjustment travel.

Changing the belt on SHK requires:

- removal of propeller
- removal of radiator
- removal of e-boxes
- removal of oil tank
- removal of ignition wiring
- removal of 4 cylinder head screws
(on a total of 6 per cylinder, very bad)

Ave. 4 to 6 hours specialized work!

Changing the belt of the Nimbus 4



A FLIGHT TEST EVALUATION OF THE ASH-26E SELF LAUNCHING 18-METER SAILPLANE

By Richard H. Johnson, Published in *Soaring Magazine*, September 1995


DESCRIPTION

The ASH-26E is the latest model high performance sailplane to be produced by the well known Alexander Schleicher Segelflug-zeugbau Company in Poppen-hausen, Germany near the famous Wasserkuppe soaring site. It is a very modern 18-meter wingspan sail-plane, and the "E" option equips it with a quiet and smooth running internally mounted Mid-West AE 50 HP self launching Wankel engine. This sailplane design

PROPULSION FAILURE

It was during this testing period that the ASH-26 suffered a propulsion system failure, and we had to resort to aero towing to finish the testing. The engine itself did not fail, but a sealed propeller drive belt idler pulley bearing failed, causing a sudden and complete loss of propeller

thrust. The cause of the bearing failure was not determined. The engine had been operated only about 18 hours total time before the bearing failed. The ASH-26 was equipped with both a nose and a CG tow hooks, so most of the testing was able to continue uninterrupted.



ASH26E: The belt drive failed during the test flight by Dick Johnson in 1995.
Only 18 hours since new...

COMPONENTS OF A THERMAL ENGINE POWER PLANT

1. Propeller
2. Reducer
3. Engine
4. Cooling circuit
5. Ignition system
6. Gasoline tanks and pipes
7. Pylon and its rotation device
8. Electrical generation and distribution
9. Control system and interlocks
10. Exhaust gas ducts and muffler

- 2-stroke: vibrations, easy access and maintenance.
 - Many problems but a lot of background
 - Problems always solved locally, even in Patagonia
- Rotating Wankel: smooth running, very temperature sensitive, less power
 - Less problems but **no** maintenance by owner
 - Less problems also because much less sold
- Electric: Just unusable in mountain, insufficient range (maxi 3.000 m per charge)

2-stroke ROTAX

A complete failure because of design errors


- ✓ Piston ring slot at wrong place
- ✓ Oil tube crimped, not secured, leaks
- ✓ ignition case cut in front of the exhaust elbow
- ✓ Original setting of magnets totally wrong (TN)

Why not use the 582? Thousands are running perfectly!

- ✓ ignition coils and pick-up changed to Bosch
- ✓ e-boxes original location totally wrong (lost in flight)
- ✓ belt change requires opening half of the cylinder head screws

How can LBA certify such a mess? On which criterion?

Rotax 535 Piston Ring position error and result (25 hours since supposedly new)








The tube is only crimped, not secured! Leaks!


Rotax 535 Oil Tube leakage

Rotax 535 Ignition Case Cut



Case cut in front of
exhaust pipe elbow

Coils and pick-up
overheat and burn




Case cut in front of
exhaust pipe elbow

Coils and pick-up
overheat and burn

Rotax 535 Ignition Case Cut

Rotax 535 Ignition Case Cut Shield



Stainless Steel shield in
front of exhaust pipe
elbow

2-stroke SOLO:

- Near to zero problem with the small “turbo”
- After initial start-up in 1998, situation is now “acceptable”, manufacturer is collaborating, spares available (only from Solo)
- BUT: still a “special” design for aircrafts. Very small production.

Why not use a fully standard and proven product?

Rotating Wankel, ex Midwest, now Diamond:

- Delicate, any work requires sending the engine to the manufacturer: high risk in remote countries.
- Very variable results: some pilots had their engine out 6 months several times, other have never experienced any problem.
- Requires running every 2 to 3 weeks, not 4 weeks as per manual. Anyhow too much for a sea shipment to Argentina.



Original Midwest spark plugs are not any more available.
New ones are bigger and all engines require machining

COMPONENTS OF A THERMAL ENGINE POWER PLANT

1. Propeller
2. Reducer
3. Engine
4. Cooling circuit
5. Ignition system
6. Gasoline tanks and pipes
7. Pylon and its rotation device
8. Electrical generation and distribution
9. Control system and interlocks
10. Exhaust gas ducts and muffler



Cooling system:

The vibration planes
of radiator and plug
are perpendicular

= breakage of the
rubber hose! Very
dangerous.

Always a spare on board!

COMPONENTS OF A THERMAL ENGINE POWER PLANT


1. Propeller
2. Reducer
3. Engine
4. Cooling circuit
- 5. Ignition system**
6. Gasoline tanks and pipes
7. Pylon and its rotation device
8. Electrical generation and distribution
9. Control system and interlocks
10. Exhaust gas ducts and muffler

Rotax 535 ignition plate

Coils (generator and ignition) have burnt out several times

Heat and vibrations





Rotax 535
ignition plate
after 17 hours
since revised
at SHK.

Then I
decided to
invest into the
Solo
conversion

- Electronic Ignition (E-boxes)
 - Ducati modified to fit Bosch ignition.
- Why not keeping the original which works beautifully on ULM?
- Every owner looking for a solution
- Both boxes lost in flight (vibrations)
- Spare connectors and a welder always on board!



Original 1998 (Rotax) and
again 2005 (Solo)

Both boxes lost in flight!



Modified by owner: no
connectors and e-
boxes at centerline of
vibrations



Modified by owner:
original connectors and
e-boxes at centerline of
vibrations



Modified by owner: no
connectors and e-
boxes at centerline of
vibrations

COMPONENTS OF A THERMAL ENGINE POWER PLANT

1. Propeller
2. Reducer
3. Engine
4. Cooling circuit
5. Ignition system
6. Gasoline tanks and pipes
7. Pylon and its rotation device
8. Electrical generation and distribution
9. Control system and interlocks
10. Exhaust gas ducts and muffler

•FUEL TANKS:

- 6 tanks in 6 years

- Extremely dangerous: requires derigging with the hands and arms swimming in the gasoline!

- After 4 years, manufacturer said to have found the reason, but not true.


- Steve Fossett: brand new ASH25Mi, already leaking (used my spare for WR)

PRESSURE TEST


According to the
manufacturer

at 1,5 mWC
pressure






We were expecting a problem at this
bad welding , but...



Every reinforcing yarn was leaking.

A drop can be seen on each one, except on the
bad weld!

Gasoline flowing
away



This vent pipe connection is badly leaking



At every refilling, all quick couplings have to be open and gasoline drops onto the electric switch.

- GASOLINE TUBES:

- What about the resistance to fire or squeeze of clear polyurethane tubes (Newly adopted)?
- Why not applying aircraft aluminium safe tubes and nipples?



Garden type quick couplings are applied on gasoline on Stemme S10! About JAR Form 1 ?

FUEL TANKS:


Cessna has been using rubber flexible tanks since 50 years on thousands of most popular and trouble free aircraft.

Why not first looking to what the others are doing?

How can LBA certify such a mess?

COMPONENTS OF A THERMAL ENGINE POWER PLANT

1. Propeller
2. Reducer
3. Engine
4. Cooling circuit
5. Ignition system
6. Gasoline tanks and pipes
- 7. Pylon and its rotation device**
8. Electrical generation and distribution
9. Control system and interlocks
10. Exhaust gas ducts and muffler




Broken coupling on a DG800



SHK Spindle support: Until September 2000, the (4) screws of the spindle drive were not secured. One fell away!

COMPONENTS OF A THERMAL ENGINE POWER PLANT


1. Propeller
2. Reducer
3. Engine
4. Cooling circuit
5. Ignition system
6. Gasoline tanks and pipes
7. Pylon and its rotation device
- 8. Electrical generation and distribution**
9. Control system and interlocks
10. Exhaust gas ducts and muffler



- The generator coil is submitted to the same vibrations and heat than the ignition coils. Same result:

- 2 failures in 120 hours with Rotax

- 1 failure after 10 hours with Solo



DG 800: the same fuse is used for charging in flight and on the ground: no more charging possible.
Engine may not move!

COMPONENTS OF A THERMAL ENGINE POWER PLANT

1. Propeller
2. Reducer
3. Engine
4. Cooling circuit
5. Ignition system
6. Gasoline tanks and pipes
7. Pylon and its rotation device
8. Electrical generation and distribution
- 9. Control system and interlocks**
10. Exhaust gas ducts and muffler


CONTROL BOX

ILEC with Binder (SHK)

DEI with DG

Many have shown problems, mainly due to vibrations and use of standard not aviation inadequate accessories

- Broken switch: engine does not move!
- Pylon limit switch seezed: idem.
- Connector not secured, falls during flight: engine does not stop and does not move!
- Fuel quantity never correct



This 1 € switch failed, impossible to retract the engine!

COMPONENTS OF A THERMAL ENGINE POWER PLANT

1. Propeller
2. Reducer
3. Engine
4. Cooling circuit
5. Ignition system
6. Gasoline tanks and pipes
7. Pylon and its rotation device
8. Electrical generation and distribution
9. Control system and interlocks
10. Exhaust gas ducts and muffler

• EXHAUST GAS

- ASH25E: springs often fail
- On Rotax 535, the elbow is too near the ignition case opening (see chapter on ignition)
- High temperature near fuselage and wires
- Almost all engines: untuned mufflers means a lot of waste power



What remains of the electric starter cable binders after 120 hours.

VIBRATIONS – Low Frequency

- Almost (not all) belt breaks occur at start on the ground. Had 4 belt breaks in 7 years
- Engine ignition firing is optimized at 6.500 rpm
- Initial firing occurs at 500-1000 rpm = engine tends to start reverse!

VARIABLE FIRING TIMING?



Décollage matinal avec Diego

VIBRATIONS – High Frequency

In 7 years, lost:

- 1 Radio
- 3 Turn & Banks
- 2 Artificial horizons
- 2 IGC loggers
- 1 Transponder
- 2 Strobe lights
- 2 Solar cell regulators

**NO SHOCK ABSORBER ON THE
INSTRUMENT PANEL !!**



Result of vibrations: the instrument panel broke on both weaker sides.

WHOSE FAULT FOR

ALL THESE

TROUBLE?

THE DESIGNER

- for inventing “crazy” solutions
- not making proper testing
- insufficient return of experience
- not following the specifications of the manufacturers of accessories
- using inadequate or low cost equipment
- not developing the culture of high risk equipment

THE DESIGNER

- for inventing “crazy” solutions
- **not making proper testing**
- insufficient return of experience
- not following the specifications of the manufacturers of accessories
- using inadequate or low cost equipment
- not developing the culture of high risk equipment

THE DESIGNER

- for inventing “crazy” solutions
- not making proper testing
- **insufficient return of experience**
- not following the specifications of the manufacturers of accessories
- using inadequate or low cost equipment
- not developing the culture of high risk equipment

THE DESIGNER

- for inventing “crazy” solutions
- not making proper testing
- insufficient return of experience
- not following the specifications of the manufacturers of accessories
- using inadequate or low cost equipment
- not developing the culture of high risk equipment

THE DESIGNER

- for inventing “crazy” solutions
- not making proper testing
- insufficient return of experience
- not following the specifications of the manufacturers of accessories
- using inadequate or low cost equipment
- not developing the culture of high risk equipment

THE DESIGNER

- for inventing “crazy” solutions
- not making proper testing
- insufficient return of experience
- not following the specifications of the manufacturers of accessories
- using inadequate or low cost equipment
- not developing the culture of high risk equipment

THE CUSTOMER

- for buying crazy systems
- paying twice its value
- keeping a low profile when a problem occurs
- not disseminating the info (with exception of the USA)

THE CUSTOMER

- for buying crazy systems
- paying twice its value
- keeping a low profile when a problem occurs
- not disseminating the info (with exception of the USA)

THE CUSTOMER

- for buying crazy systems
- paying twice its value
- keeping a low profile when a problem occurs
- not disseminating the info (with exception of the USA)

THE CUSTOMER

- for buying crazy systems
- paying twice its value
- keeping a low profile when a problem occurs
- not disseminating the info (with exception of the USA)

THE CERTIFYING BODY (LBA)

- Certifying crazy or obviously unsafe solutions (e.g. ignition, gasoline, wiring, engine modifications, etc.)
- Certifying workshops showing a clearly poor workmanship
- Certifying without knowledge

THE CERTIFYING BODY (LBA)

- Certifying crazy or obviously unsafe solutions (e.g. ignition, gasoline, wiring, engine modifications, etc.)
- Certifying workshops showing a clearly poor workmanship
- Certifying without knowledge

THE CERTIFYING BODY (LBA)

- Certifying crazy or obviously unsafe solutions (e.g. ignition, gasoline, wiring, engine modifications, etc.)
- Certifying workshops showing a clearly poor workmanship
- Certifying without knowledge

THE WAY FOR PROGRESS IS FREEDOM

- Create a special category for the motorization of gliders
- Issue recommendations for design criterion, accessories
- Allow owners and reliable mechanics to apply modifications when reasonably sound

THE WAY FOR PROGRESS IS FREEDOM

- Cancel the monopoly of so-called “certified” workshops (the worse result ever seen!)
- Transfer responsibility to the owner.




Return from a "certified" german workshop: a nut was found within the magnet group...




Starter cable (POSITIVE) few hours after return from a "certified" german workshop.

The gear was painted before tightening the screws: vibrations made all unscrewed away, gear lost.



6 VIS
SECTIONNEES



Engine back from Total Overhaul by German "certified" workshop: timing screws unsecured went away, glider grounded for months

HELP CUTTING COSTS!

- Why should we pay the standard belt 182 € at Binder's and 128 € (+ 42%) at the corner's shop?
- Why should we pay 3.000 € for a mandatory TBO when the engine was OK before and fails right after
- Why not a guarantee in hours, not calendar, like for cars?

HELP CUTTING COSTS!

- Why should we pay the standard belt 182 € at Binder's and 128 € (+ 42%) at the corner's shop?
- Why should we pay 3.000 € for a mandatory TBO when the engine was OK before and fails right after
- Why not a guarantee in hours, not calendar, like for cars?

HELP CUTTING COSTS!

- Why should we pay the standard belt 182 € at Binder's and 128 € (+ 42%) at the corner's shop?
- Why should we pay 3.000 € for a mandatory TBO when the engine was OK before and fails right after
- Why not a guarantee in hours, not calendar, like for cars?



HOLIDAY IN PATAGONIA

**NEVER FORGET THAT
YOU ALWAYS NEED AN
ENGINE...**



THANK YOU FOR YOUR ATTENTION !